

NEW YORK STATE OFFICE OF PROBATION AND CORRECTIONAL ALTERNATIVES
PRELIMINARY QUALIFIED MANUFACTURER LISTING
LAST ISSUE DATE: May 27, 2010 UPDATED: July 15, 2010

Qualified Manufacturer	Region(s) of Operation	Device Models and Classifications
1A Smart Start, Inc. CEO: Lamar Ball 4850 Plaza Drive Irving, TX 75063 LBall@SmartStartInc.com (800)-880-3394	1, 2, 3 & 4	-Smart Start SSI-1000 CLASS I -Smart Start 2020 CLASS III
Alcohol Countermeasure Systems Corp CEO: Felix J. E. Comeau 60 International Boulevard Toronto, Ontario CANADA M9W6J2 fjecomeau@acs-corp.com (416)-619-3500	4	-Alcolock WR2 CLASS I -Alcolock WR3 CLASS I
Consumer Safety Technology, Inc. CEO: David Arringdale 10520 Hickman Rd., Suite F Des Moines, IA 50325 DArringdale@cstinc.com (515)-331-7643	1, 2, 3 & 4	-Intoxalock 1001A CLASS I -Intoxalock 1001A with Advanced Wireless Technology CLASS III
Draeger Safety Diagnostics, Inc. CEO: George W. Ballance 4040 W. Royal Lane, Suite 136 Irving, TX 75063 George.ballance@draeger.com (972)-929-1100	1, 2, 3 & 4	-Draeger XT * CLASS III *Available August 15, 2010
Interceptor Ignition Interlocks, Inc. CEO: John Ruocco 45 Ramsey Rd. Unit 23 Shirley, New York 11967 jroc@interceptorusa.com (631)-205-0791	1, 2, 3 & 4	- Interceptor M-1 CLASS III
National Interlock Service (NY) Ltd. CEO: Michael R. Balgord 660 Aaron Court Kingston, NY 12401 nisny@nationalinterlock.com (800)-871-5462	1, 2, 3 & 4	-LifeSafer FC100(no camera) CLASS I -LifeSafer FC100 (camera) CLASS III
Sens-O-Lock of America, LLC CEO: F. Craig Lotz 12544 SE 90 th Terrace Summerfield, FL 34491 clotz@sensolockamerica.com (404)-748-4484	1, 2, 3 & 4	-BEST LABS FR9000 CLASS I